Software and Configuration Changes

Microsoft Change	Microsoft's Announced Implementation Date*	Required Ribbon Platform Changes		
		Edge SBC	**Intelligent Edge**	**Core SBC**
MC299923: Direct Routing SIP interface will only trust certificates that are signed by Certificate Authorities (CAs) that are part of the Microsoft Trusted Root Certificate Program.	**January 3, 2022***	None.	None.	None.
M307310: Microsoft's updated SIP signaling FQDN range to include IP subnet range and no longer use sip-all.pstnhub.microsoft.com.	**March 1, 2022***	Yes[1]. Suggested software upgrade to 9.0.7 and 11.0.1. Availability targeted for Q1 2022	Yes[2]. Software upgrade to VOS 16.x, 15.x. Availability targeted for Q1 2022	None. Follow Ribbon Microsoft Teams guide.
MC299922: Direct Routing will stop processing SIP requests which have 'Replaces' headers.	**April 1, 2022***	Yes. Required. software upgrade to 9.0.7 and 11.0.1. Availability targeted for Q1 2022	None.	None.

* - Microsoft may unilaterally change implementation dates. Please refer to the Microsoft link provided for each of the changes to confirm implementation timelines.

[1] – Customers can manually make configuration changes to the existing software releases to support federated IP addresses for Microsoft Teams SIP trunks. However, you cannot use the platform's configuration wizard to make changes or set up new trunks. A software upgrade is required to update the platform's built-in configuration wizard.

[2] – Software change is required to update the trusted list in the Microsoft Teams Routing Group configuration of the EdgeMarc to the recommended IP range Microsoft recommends.